Qty:

Date: User: Monday, 06/10/2008 1:21:16 PM

Julie Lecocq

Process Sheet

Customer Job Number : CU-DAR001 Dart Helicopters Services

: 42480

Estimate Number

: 13311

P.O. Number

: 06/10/2008 This Issue

Prsht Rev. : NC

First Issue Previous Run

: // : 40553 Type

S.O. No. :

: SMALL /MED FAB

Part Number

Drawing Name

: D37941

Drawing Number

: D3794 REVA : N/A

: GASKET

Project Number : A **Drawing Revision**

Material

Due Date

: 20/10/2008

20 Um:

Each

Written By Checked & Approved By

Comment

: Est Rev:A 08-05-13 Est Rev:B

08-05-23

new issue DD verified by:EC revA as per dwg DD verified by:EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

MNEO60S063 1.0

NEOPRENE SHEET 0.063

Comment: Qty.:

0.6197 sf(s)/Unit

Total:

12.3942 sf(s)

NEOPRENE SHEET 0.063

Batch: 16881 &-10-14

2.0

WATER JET

FLOW WATER JET



Comment: FLOW WATER JET

1-Cut as per Dwg D3794

Dwg Rev:_ Prog Rev:__ 1B8-10-14

2-Deburr if necessary

QC2

HS 8-10-14

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

3.0

QC8

SECOND CHECK

Comment: SECOND CHECK

5.0

PACKAGING 1

counter

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

Page 1

Form: rprocess

Dart Aerospace Ltd

Dail Aci	Ospace	Liu							
W/O:			WO	RK ORDER CHANG	ES		·		·
DATE	STEP	PRO	OCEDURE CHAN	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		: `							
							ļ		
		,							·
Part No	:	PAR #:	Fault Categ	gory:	NCR: Yes	No DQ	A :	_ Date: _	
	R	esolution:	Disposition	n:	_ QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR	R)			
D. 4.7.F	0750	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
				·					
	1				1	1		1	1

NOTE: Date & initial all entries

Date: User: Monday, 06/10/2008 1:21:16 PM

Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: GASKET

Job Number: 42480

Part Number: D37941

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL TION/W/O RELEASE

Job Completion



Dart Aerospace Ltd	Dart	ace Ltd
--------------------	------	---------

	oopaoc											
W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								1				
			·							·		
Part No	•	PAR #:			NC	R: Yes	No DQ	A :	Date:			
	R	esolution:	Dispositio	n:	QA	N/C Clo	sed:		Date: _			
NCR:			WORK ORD	ER NON-CONFORM	MANCE	(NCR)					
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Some Action Description Chief Eng	ection B n	Sign & Date	Verific Secti		Approval Chief Eng	Approval QC Inspector		
			Office Eng	Chief Eng		Date			•			
		·						•				

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	12480
Description: Gasket	Part Number:	D3794-1
Inspection Dwg: D3794 Rev: A		Page 1 of 1

•	FIRST	ARTICLE IN	SPECTION	ON CHE	CKLIST		
	X	First Artic	le	Proto	type		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Con	nments
Ø0.19	+0.005/-0.001	.192	¥				·
0.300 x 0.300	+/-0.010	303 × 303	*				
1.88	+/-0.030	1.888	X			· .	
0.90	+/-0.030	,90	×				
3.90	+/-0.030	3.888	*				_
8.00	+/-0.030	9.00	¥				
14.00	+/-0.030	14.00	*				
20.00	+/-0.030	20.00	7		·		
14.07	+/-0.030	14.67	4				•:
18.98	+/-0.030	18.98	8				
23.90	+/-0.030	29.90	¥			_	
27.40	+/-0.030	27.40	Y				
29.40	+/-0.030	29.40	A			<u>-</u>	· -
32.90	+/-0.030	32,96	*				
					·		
					-		
		-					
Measured by: 18		Audited by:	5.		Prototype App	oroval:	N/A
	-10-14	Date:	05/10	Date:			N/A
	hange	1	7.000		Revised	d by	Approved
	ew Issue				KJ/DD	all.	N N

